

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**CL445**  
**SW**  
**1/2-1**  
**0.701 mi.**  
**3701 ft.**

**ROAWAY/SEWER**  
**SURF AVE AND WEST 23RD ST**  
**BROOKLYN, NY**

**NY Spills** **S113817263**  
**N/A**

**Site 2 of 3 in cluster CL**

**Relative:**  
**Higher**

**Actual:**  
**3 ft.**

**SPILLS:**

Name: ROAWAY/SEWER  
Address: SURF AVE AND WEST 23RD ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1302019 / 2013-06-03  
Facility ID: 1302019  
Facility Type: ER  
DER Facility ID: 437690  
Site ID: 482440  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: Not reported  
SWIS: 2401  
Spill Date: 2013-05-28  
Investigator: SMSANGES  
Referred To: Not reported  
Reported to Dept: 2013-05-28  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial Vehicle  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2013-05-28  
Spill Record Last Update: 2013-06-03  
Spiller Name: SHERRY BOLKEY  
Spiller Company: NYC TRANSIT  
Spiller Address: SURF AVE AND WEST 23RD ST  
Spiller Company: 999  
Contact Name: SHERRY BOLKEY  
DEC Memo: ""  
Remarks: "unk amt onto roadway and sewer, c/u and investigation pending.  
----- 14:31 - Caller updated location and change material to  
transmission fluid, 1/2 of which made it into sewer. All cleanup is  
complete."

**All Materials:**

Site ID: 482440  
Operable Unit ID: 1232172  
Operable Unit: 01  
Material ID: 2230966  
Material Code: 0021  
Material Name: transmission fluid  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .50  
Units: G  
Recovered: Not reported  
Oxygenate: Not reported